TECHNICAL DATA SHEET



UNDERCOAT

A traditional solvent-borne intermediate coating providing excellent covering power and adhesion, hides imperfections and helps provide the perfect foundation for the Crown Contract Finishes. It is perfect for wood and metal that has been previously primed or painted

AVAILABILITY		
Colour	White	
Packaging	1L and 2.5L	
PROPERTIES		
Suitable Surfaces	Suitably prepared interior & exterior wood and metal surfaces	
Drying Time @ 20*C/65%RH	Under normal drying conditions touch dry in 4-6 hours and recoat after 16 hours. Allow for	
	adequate ventilation during the drying period.	
Finish	Matt	
Composition	Pigment: Titanium Dioxide and extenders	
	Binder: Resin: Alkyd	
Spreading Rate	Solvent: Dearomatised White Spirit Up to 15m² per litre on smooth surfaces	
Wet Film Thickness	66 micrometres at 15m² per litre	
Dry Film Thickness	34 micrometres at 15m² per litre.	
Volume Solids	52%.	
Flash Point		
	40°C (closed cup).	
VOC Content	EU limit value for this product (cat.A/d): 300 g/l (2010). This product contains max. 299 g/l	
	VOC.	
Limitations	Do not apply when air or substrate temperatures are likely to fall below 8°C or when the	
	relative humidity is above 80% during application or the drying period. Do not over apply.	
PREPARATION		
All New Metals	Lightly abrade to a bright (not polished) surface, excluding galvanised surfaces. Wash with	
	hot water and liquid detergent solution to remove oil, grease or any other contaminants,	
	frequently changing the water. Rinse thoroughly with clean water. Allow to dry. When dry	
	prime with one coat of Crown Contract All Purpose Primer followed by one coat of	
	Crown Contract Undercoat.	
Galvanised Metal	Bright galvanised surfaces should be thoroughly degreased as per new metals, then pre-	
	treated with a T Wash. Overall blackening of the surface will confirm satisfactory surface	
	degreasing. When dry prime with one coat of Crown Contract All Purpose Primer	



TECHNICAL DATA SHEET



	followed by one coat of Crown Contract Undercoat.
Non Ferrous Metals	Prime bare metal with one coat of Crown Contract All Purpose Primer followed by one
	coat of Crown Contract Undercoat.
Ferrous Metals	Remove all millscale and surface rust back to clean bright metal. Remove all residues.
	Prime within the working day with one coat of Crown Contract All Purpose Primer
	followed by one coat of Crown Contract Undercoat.
Previously Decorated Metal	All surfaces must be suitably dry, and free from anything that will interfere with the adhesion
Surfaces	of the materials to be applied. Remove all loose and failing or suspect paint. Organic
	growth must be treated with Sandtex Trade Fungicidal Solution and removed. Feather
	edges of sound paint. Remove all dust. Remove all rust. Spot prime all bare metalwork with
	Crown Contract All Purpose Primer. Wash remaining sound paint with hot water and
	liquid detergent solution to remove any contaminants, frequently changing the water. Wet
	abrade to provide a key. Rinse with clean water to remove all residues. Allow to dry. Bring
	forward spot primed areas with one coat of Crown Contract Undercoat.
New Wood Surfaces	All surfaces must be sound, clean, suitably dry and free from anything that will interfere with
	the adhesion of the materials to be applied. Rub down with a suitable grade of abrasive
	paper and round sharp edges to a 1-3mm radius. Remove all dust. Timber with
	oils/extractives must be swabbed with clean methylated spirits, frequently changing the
	face of the cloths. Treat any knots with two coats of fresh knotting. Fill any fixing holes,
	open joints and shallow surface defects with Sandtex Ready Mixed Filler or 2 pack wood
	filler. Prior to priming with one coat of Crown Contract Quick Dry Primer Undercoat the
	moisture content of the substrate should not exceed 18% Apply one coat of Crown
	Contract Undercoat.
Previously Decorated Wood	All surfaces must be sound, clean, suitably dry and free from anything that will interfere with
Surfaces	the adhesion of the materials to be applied. Remove all loose, failing or suspect paint.
	Remove grey and denatured surfaces by rubbing down with abrasive paper. Feather
	edges of sound paint. Remove all dust. Organic growth must be treated with Sandtex
	Trade Fungicidal Solution and removed. Remove any defective putty glazing, clean and
	prime rebates, replacement putties must be allowed to form a hard skin. Treat knots with
	two thin coats of fresh knotting. Fill any fixing holes, cracks and shallow surface defects
	with Sandtex Ready Mixed Filler or 2 pack wood filler. Wash remaining sound paint with
	hot water and liquid detergent solution to remove any contaminants, frequently changing
	the water. Wet abrade to provide a key. Rinse with clean water to remove all residues.
	Allow to dry. Prior to priming the moisture content of the substrate should not exceed 18%
	Spot prime bare and filled areas with one coat of Crown Contract Quick Dry Primer



TECHNICAL DATA SHEET



	Undercoat followed by one coat of Crown Contract Undercoat
COATING SYSTEM*	Apply one coat.
	*Certain colours or substrate design may require additional coats to achieve full opacity.
APPLICATION	Stir well before and during use. Apply using good quality tools – synthetic or bristle brush or
	short/medium pile roller. Maintain a wet edge.
	Always intermix (box) packs for colour consistency. Please check for colour accuracy prior
	to application. Crown Paints is not liable for decorating costs caused as a result of an
	incorrect colour being applied.
CLEANING	Return surplus material to container. Clean tools & equipment with a
	proprietary cleaner immediately after use.
STORAGE	Store upright and secure. Store in secure dry conditions inaccessible to children or
	animals. Containers should be kept closed during storage. Do not store below 5°C or
	above 40°C.
MAINTENANCE INFORMATION	Between maintenance redecoration, surfaces may be washed with a warm water and liquid
	detergent solution to remove surface dirt.
HEALTH AND SAFETY	Please refer to the Safety, Health and Environmental Information on the container. Take
	special precautions during the surface preparation of pre 1960's painted surfaces as they
	may contain harmful lead. For further information contact the Customer Relations Team.
	When preparing all surfaces avoid the inhalation of dust and/or metal particles. Wear a
	suitable facemask. Material Safety Data Sheets for this and all other Crown Paints
	products are freely available from the place of purchase or the address below. Do not
	empty into drains, watercourses or access routes to septic tanks.
GENERAL INFORMATION	Apply all products in accordance with BS 6150: Code of practice for painting of buildings
	and BS 8000: Part 12: Code of practice for decorative wallcoverings and painting.
	Every care is taken to ensure that all information provided on this Technical Data Sheet is
	accurate. Crown Paints is unable to guarantee results as it has no control over the
	conditions under which its products are applied.
	Before using this product, please ensure you have the latest information. For help or more
	information contact the Crown Contract Customer Relations Team on: Tel: 0330 0240281
	Fax: 0330 0240261
	e-mail: info@crowncontract.co.uk
	website: www.crowncontract.co.uk
	This information is correct at date of issue November 2021.

